



Appendix E – Transient Calibration Bore Hydrographs




WellArc 206 - Site 4380003 Hukatere Piezo at Houhora




WellArc 207 - Site 4381007 Forest Piezo at Houhora




WellArc 208 - Site 4381005 Browne Piezo at Houhora




WellArc 209 - Site 4381009 Burnage Rd Piezo at Houhora



WellArc 211 - Site 4392001 Paparore Rd Piezo at Paparore



WellArc 081 - Site 5301001 Ogle Drive at Paparore



WellArc 226 - Site 5301003 Lake Heather No.1

