




Layer 1



Layer 2



Layer 3



Layer 4




Figure 35. December 2006 model piezometric surfaces following closure of all flowing artesian bores.