

Kaihu right bank from Waihue Road to Taita Stream confluence, and Taita Stream left bank from confluence to SH12 (survey RB5)

- - - Estimated natural unmodified bank level
- Bank crest surveyed 2010
- Maximum water level in 6 month ARI flood, with no bank overtopping
- - - Maximum water level in 1 year ARI flood, with no bank overtopping



